

C.L. "BUTCH" OTTER – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

April 12, 2007

Ryan Rasmussen, Administrator Turtle & Crane 1950 First Street Idaho Falls, ID 83401

License #: RC-857

Dear Mr. Rasmussen:

On March 1, 2007, a life safety code survey was conducted at Turtle & Crane. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

March 6, 2007

Ryan Rasmussen, Administrator Turtle & Crane 1950 First Street Idaho Falls, ID 83401

Dear Mr. Rasmussen:

On March 1, 2007, a life safety code survey was conducted at Turtle & Crane. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 31, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

(X3) DATE SURVEY

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES

(X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - BUILDING 1 B. WING 13R857 03/01/2007 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 1950 FIRST STREET **TURTLE & CRANE IDAHO FALLS, ID 83401** (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION in (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PRÉFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on March 01, 2007. The surveyor conducting the survey was: **Taylor Barkley** Health Facility Surveyor Facility Fire safety & Construction Bureau of Facility Standards TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

If continuation sheet 1 of 1 STATE FORM Q3N521



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

Facility Name	Physical Address	Phone Number
Turtle And Crave	1950 1st STreet	(208) 557-0186
Administrator	City	ZIP Code
RYAN RASMUSSEN	Idaho Falls	83461
Survey Team Leader	Survey Type	Survey Date
TAYLOR BArkley		3-1-7

	MOR I	BAIRley 3-1	-7	
NON	-CORE ISSU	ES	•	
ITEM #	RULE# 16.03.22	DESCRIPTION	DATE RESOLVED	BFS
1	405.05	A. Rosilent Room #4 in building #1 is missing the sprinkler head		
		cover in the bathroom.		
		B. The laundry room in building the has a one half in hole		226 070 07
		In the ceiling around the sprinkler head.		
*	,	c. The mechanical rooms in both building # 1 and		
		building to have multiple nine and conduit penetra	thus	
		That have not been sealed.	W-100	
		D. The mechanical closet in the launday room of building	26	
		# a has nultiple penetrations of the ceiling.		33.00.00
		E. Resident Room #15 in building # 2 is missing the		
		sprinkler head cover in the bathroom.		
<u> 2.</u>	250.10	The facility has a hot water temperature of 133,6°F.		100 000 0
3	1116			
	1912,03	The facility has not conducted monthly Sire extinguisher		
		check.		
Respons	se Required Date	Signature of Facility Representative	Date Signed	
4-	1-7	Annaly farmis	2/1/07	
				····